


Corrigendum

CIBSE Guide B4 (2016): Noise and vibration control for building services systems

Page 4-84 Figure 4.63 should be replaced by:



26.09.16